
a
Sheet Resistance R_{xx}(T) (kΩ/□)
Temperature (K)
A-type
Sample A
b
Sheet Resistance R_{xx}(T) (Ω/□)
Temperature (K)
B-type 1
B-type 2
Sample B
c
Hall Resistance $R_{A_{xy}}$(H) (Ω)
Magnetic Field (T)
A-type
$3x10^{13}cm^{-2}$
Sample A
$2.3x10^{13}cm^{-2}$
T = 1.5K
d
B-type Hall Resistance R_{xy}(H) (Ω)
Sample B Hall Resistance R_{xy}(H) (Ω)
Magnetic Field (T)
B-type 1,
$7.6x10^{15}cm^{-2}$
Sample B,
$6.4x10^{14}cm^{-2}$
T = 1.5K
e
$R_{xx}(H_{//})$ (kΩ/□)
0.1K
0.5K
Sweep Up
Sweep Down
Sweep Back Up
T = 0.1K
Magnetic Field (T)
f
$R_{xx}(H_{//})$ (Ω/□)
$R_{xx}(H) - R_{bg}(H)$ (mΩ/□)
1/Magnetic Field (T^{-1})
0.1K, H > 0
0.1K, H<0
0.08K, H>0
Sweep Up
Sweep Down
T = 0.1K
Magnetic Field (T)