

**OFF**

$$\begin{aligned}\dot{x} &= -0.002(x - 16) \\ \dot{y} &= 0\end{aligned}$$

**Heating**

$$\begin{aligned}\dot{x} &= -0.002(x - y) \\ \dot{y} &= 0.1\end{aligned}$$

$$\begin{aligned}\dot{x} &= -0.002(x - y) \\ \dot{y} &= -0.1\end{aligned}$$

**Cooling**

$$\begin{aligned}\dot{x} &= -0.002(x - y) \\ \dot{y} &= 0\end{aligned}$$

**ON**

